

PRODUCT BULLETIN

DATE: December 2, 2004

TO: All Dunkirk Customers

SUBJECT: Q90-100 Series Boilers - Hot Surface Igniter Change

The Q90 50-100 series of boilers are now being manufactured utilizing a Norton brand hot surface igniter. The previously used igniter has been phased out and replaced by the Norton igniter. Both igniters continue to be approved for use with the Q90 50-100 series of boilers and are cross compatible.

The shape (see Fig. 1) of the Norton igniter creates a larger surface area resulting in improved ignition. This is especially helpful for LP gas. The Norton Igniter has also proved to be more robust, increasing igniter life.




Fig. 1

The part number for the replacement igniter kit will remain 43800013.

If you have any questions, please feel free to contact the Dunkirk Technical Service staff at 1-877-Dunkirk (387-5475).